


Photos of some staybolt installations





Photos of offset where rear of crown sheet is joined to door sheet



photos of area where radial stays have been removed

